

Impact of Combustion Turbine Upgrades on HRSGs

By: Anand Gopa Kumar Analysis Manager, HRST Inc.

IDEA2019 Pittsburg, PA June 24-27, 2019



Combustion Turbine Upgrades – Driving Factors

- Disruption in the North American power market from renewables
- Combined cycle units stepping in to support renewables
- Increasing need for turndown operation of combustion turbines
- Need for Peak Capacity, Low load and spinning reserve requirements are increasing in the current power market
- CT Upgrades become a logical solution to address these issues






Combustion Turbine Upgrades

CT Upgrades – Typical Expectations

- Increased output by 3%-10%
- Decreased heat rate by 0.5%-1.5%
- Increased exhaust gas temperatures (~+50°F at base load)
- Increased exhaust gas flow rate (0.1%-2% at base load)
- Higher exhaust gas temperatures at startup/low load (+1200°F)

Impact on HRSG Post-Upgrade - What Happens?

- During base load operation with and without supplemental burner firing
- Low Load / Part Load Operation



Combustion Turbine Upgrades – Key Concerns

Increased Temperature

- Overheat of Tubes, headers and piping
- Non pressure part overheat (tube ties, baffles, liners, etc.)
- Attemperator Overspray
- Low Load Capabilities and Emissions

Increased Energy

- Steam production
- Will a re-rate be needed?
- Safety valve capacities
- Final steam separator design limits


Increased Exhaust Flow Rate

- Proper catalyst sizing
- Gas side pressure effects on casing, expansion joints and upstream module penetration seals




Tube Metal Temperatures

- TMT is between steam and gas temperature
- Proportion remains constant before and after upgrade
- Temperature of metal increases with increased gas temperature
- If gas temperature increases significantly the TMT could overheat the tube




Tube Metal Temperatures

- CT Upgrades can push TMT over design limits
- "Low Load Unfired" operation can be the limiting case for HP Superheater and Reheater Tubes
- Note: CT hits ~1215°F isotherm at a lower ambient temperature after upgrade – Low load cases experience higher gas temperatures
- Even if TMT design limit is not exceeded, the service life of the pressure parts are reduced




Tube Overheat

- Overheat results in oxide layer growth on the tube surface
- Oxide layer acts as an insulator in the path of heat transfer increasing the tube metal temperature
- Cyclical operation with an overheating tube results in exfoliation and eventual failure






Tube Metal Temperatures – Internal Oxide Growth




Creep in Reheaters and Superheaters

- Small changes in metal temperatures can significantly reduce creep life
- Calculated using Larson Miller Parameter (LMP)
- Grade 22
 - 1070°F / 577 C ~185,000 hrs
 - 1080°F / 582 C ~130,000 hrs
 - 30% life decrease*
- Grade 91
 - 1110°F / 599 C ~169,000 hrs
 - 1120°F / 604 C ~100,000 hrs
 - 40% life decrease*

*<u>Note:</u> the remaining life is a function of both operating pressure and tube thickness as shown in box above graph



Attemperator Overspray Risk



Effect of TEG Temp on Residual Superheat

Post Upgrade Conditions:


- Final steam temperature still at ~1050°F
- Exhaust gas temperature & massflow increase to Module 1

<u>Result:</u>

- Higher attemperator spray water flow required to maintain the final steam temperature setpoint
- Attemperator and control valve could run out of capacity
- Higher spray flow rate could mean "overspray" and pressure part damage downstream.

Case Study 1 – RH SH Tube Failure

- Frame 7F unit underwent CT Upgrade
- CT Exhaust Gas temperature increased by about 50°F after the upgrade
- Duct Burner was operating at the same high firing rate after upgrade
- Higher burner inlet gas inlet temp and high pre upgrade firing rate caused burner outlet temperature be higher after upgrade





Case Study 1 – RH SH Tube Failure

- Post upgrade operation with high firing rate resulted in failure of Reheater tube immediately downstream of burner
- HRST performed an RCFA of the failure
- Metallurgical assessment revealed failure mechanism as Long Term Overheat






Case Study 1 – RH SH Tube Failure



Fissures and Oxide Layer on ID of Tube

RH SH Tube Specs: 2.5 inch OD 0.12 inch min wall Material: T23 (ASTM A213/SA-213) Design Pressure: 650 psig Design Temp: 1119°F



Higher Exhaust Gas Energy

- Higher than expected energy going into the HRSGs
- Higher steam production can be expected due to the increased energy which could potentially exceeding the nameplate capacity
- New operating conditions could lie beyond the relieving capacities of the installed PSVs
- Higher amount of interstage attemperation required to control final steam temperature



Case Study 2 – Post Upgrade Steaming Capacity

- GE 7FA turbine, 3 pressure w/RH HRSG, 2x1 configuration, no duct burner
- Client approached HRST prior to CT Upgrade for an assessment
- Additional attemperation required after upgrade
- Thermal modeling determined HP Steam flow increase by 2-5% post upgrade
- This causes HRSG to exceed rated capacity and PSV capacities

	High Pressure	IP/ Reheat	Low Pressure
	(HP)	(RH)	(LP)
Current Name Plate Capacities	573,135 lb/hr	606,294 lb/hr	39,255 lb/hr
Current Pressure Safety Valve Capacity	579,619 lb/hr	614,193 lb/hr	40,673 lb/hr
Calculated expected max flow after AGP upgrade	591,245 lb/hr	632,194 lb/hr	29,731 lb/hr



Case Study 2 – Post Upgrade Steaming Capacity

Additional Checks included:

- 1. Superheater tube metal temperatures
- 2. Superheater header design temperatures
- 3. Inlet duct liner & insulation temperature limits
- 4. SCR gas inlet temperatures
- 5. Boiler Feed Pump capacity
- 6. Feedwater control valve sizing
- 7. Steam and water side pressure drops
- 8. Steam drum separator capacity
- 9. Safety valve relieving capacity.



Results:

- New specifications of PSVs provided to client.
- Re-rate of the HRSG nameplate was required with an R-stamp

CT Upgrade Considerations on Catalysts

- Increased CT Gas Flow Rate Decreased residence time in catalyst
- Variation in Exhaust Gas Temperature Decreases catalyst effectiveness
- Temperature also plays a key role in catalyst fouling
- What happens at low load after upgrade? Gas temperatures could be lower after upgrade



Non-Pressure Overheat

- Non-pressure parts operating close to or above design temperatures
- Areas affected
 - Perforated Plate (Flow Distribution Grid)
 - Tube ties
 - Baffles
 - Flow devices
 - Inlet Duct Liner
 - Firing Duct Liner





Non-Pressure Overheat





Conclusions - Things to Consider ...

Before an Upgrade

HRSG Rated Capacity

- Post upgrade steam generation
- PSV relieving capacity

Overheat Concerns

- Possibility of tube TMT exceeding design temperature
- Existing overheat damage in HP&RH Superheaters
- Evaluate full load <u>and</u> low load!

Catalysts, Pumps, Valves

- Catalyst residence time and operating temperature shift
- Will attemperators, control valves and pump limits be exceeded?

After an Upgrade

- Is the pre-upgrade operational profile still valid?
 - Can burner operation be the same?
 - Low load operation

Indications of overheat?

- Look for indications of overheat outside and possibly inside panels
- Monitor condition of inlet duct and firing duct liner for signs of overheat
- Observe attemperator operation, are there indications of overspray or difficulty maintaining setpoint temperature



Conclusions – The Big Picture

HRSG Areas Impacted by CT Upgrades = **Steam Separators** Safety Valves Steam Capacity Perf Burner Plate Duct CO/SCR Inlet Catalyst Duct TMT Attemperators

Additional Areas of Concern

- Boiler Feed Pump
- Recirculation Pump
- Drum Level Control Valves







Questions ?

Anand Gopa Kumar agopakumar@hrstinc.com 952-767-8145

info@hrstinc.com | www.hrstinc.com 6557 City West Parkway Eden Prairie, MN 55344 1-952-767-8100